

Annexure D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: 11/12/24

It is certified that the existing building Crescent School building (name of the building or premises) at Vandalur Chemis. CBSE

Gx floor + First floor (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block <u>Gx + FF</u>	<u>Section 1 to 12 class</u>					

The building is owned/occupied by Crescent School, Vandalur (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of E. Kannakarasu (Name of Department/ Govt.) on 11/12/24 (date of inspection) in the presence of Mrs. P. Manimegalai, Crescent School, Vandalur, ch-48 (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 11/12/24 for a period of three years in accordance with rule and subject to compliance of the specific conditions as appended.

- Stability of building ensures
-
-
-

Issued on 11/12/24 at Kattankolathur by _____

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: [Signature] 11/12/24

Name: E. Kannakarasu

Designation: Assistant Engineer

Name & Address of Department/ Office: R.D. Office Kattankolathur Dist. Chengalpattu Dist.

**ASSISTANT ENGINEER(RD)
KATTANKOLATHUR BLOCK**